

Steering CV

Criteria:

Identification

Completeness

Mechanical damage

Corrosion



Steering CV

Criteria:

Identification

Order of identification:

- factory number (e.g. starting with 80...955...) on the part or
- Bosch exchange number (e.g. starting with 80... or KS ...) on the part or
- Bosch exchange number (e.g. starting with 80... or KS ...) on the box



Acceptable



Acceptable

Steering CV

Criteria:

Completeness

Partly dismantled is not acceptable;
Nut of worm gear missing is acceptable



Not acceptable



Acceptable

Steering CV

Criteria:

Mechanical damage

Gearing damaged is not acceptable



Acceptable



Not acceptable

Steering CV

Criteria:

Mechanical damage

Housing damaged is not acceptable



Acceptable



Not acceptable

Steering CV

Criteria:

Mechanical damage

Housing damaged is not acceptable



Not acceptable



Not acceptable

Steering CV

Criteria:

Corrosion

Strong corrosion/water damage is not acceptable



Not acceptable



Not acceptable

Steering CV

Criteria:

Corrosion

Strong corrosion/water damage is not acceptable



Not acceptable

Steering CV

Additional remark:

For safety reasons please check if plugs are in place. If plugs are missing please apply plugs to avoid oil leakage. Only this way, it can be avoided that oil leaks from the steering. This process needs to be done here: Back side and label side.



Missing plug

apply plug

screw plug tightly



Missing plug

apply plug

screw plug tightly

Steering CV

Additional remark:

Steering cleaned and stored safely for transportation.
Put steering properly in box together.
Do not stack steering without layer in between.



Acceptable



Not acceptable